







Assembly Instructions



23027







60 min









		23027
1	1	1600x400x18MM
2	1	1600x400x18MM
3	2	398x314x18MM
4A	1	379x314x18MM
4B	1	379x314x18MM
5	1	522x363x18MM
6A	1	518x310x36MM
6B	1	518x310x36MM
7A	2	512x324x5MM
7B	1	532x324x5MM
8	1	518x164x18MM
9A	1	332x100x18MM
9B	1	332x100x18MM
10	1	501x100x18MM
11	1	475x342x5MM






 ϕ 15x12 Ax16	 M6x35 Bx16	 ϕ 8x40 Cx20	 M3.5x15 Dx54
 350mm Ex2	 M6x24 Fx8	 Gx2	 Hx1
 Ix4	 Jx12	 Kx8	 Lx12
 Mx1	 Nx1	 Ox1	 Px1
 Qx4	 Rx9	 Sx6	 Tx3
 Ux3			





1





$$E=E1+E2$$




2





3




4




5



6




7



8




Ax8




9-15


9



10



Bx8




10-15

11



Ax8




12



Dx12





Jx12




11-15

13




14




12-15

15




16




13-15

17





18





14-15

19



20



15-15